



0h 30mn



FR SECURITE

RESPECTER LES INSTRUCTIONS DE MONTAGE DECRITES DANS LA NOTICE.

EN CAUTION

FOLLOW CAREFULLY THE ASSEMBLING INSTRUCTIONS DESCRIBED IN THE DIRECTIONS.

DE SICHERHEITSVORSCHRIFTEN

BEACHTEN SIE BITTE UNBEDINGT DIE ANGEGBENEN AUFBAUVORSCHRIFTEN.

ES SEGURIDAD

RESPECTAR LAS INSTRUCCIONES DE MONTAJE DESCRIBIDAS EN EL FOLLETO.

NL VEILIGHEID

DE IN DE GEBRUIKSAANWIJZING BESCHREVEN INSTRUCTIES RESPECTEREN.

IT SICUREZZA


RISPETTARE LE ISTRUZIONI DI MONTAGGIO DESCRITTE NEEL'AVVERTENZA.

PT SEGURANCA


RESPEITAR AS INSTURAOES DE MONTAGEM DESCREVIDAS NA INSTRUÇÕES DE USO.

PL UWAGA


PROSZĘ PRZESTRZEGAĆ INSTRUKCJI MONTAŻU.



REP	DIM	QTE
1	366 x 294	1
2	366 x 294	1
3	366 x 295	1
4	332 x 293	1
5	328 x 123	1
6	332 x 59	1
7	309 x 248	1
8	250 x 100	1
9	299 x 100	1
10	250 x 100	1
11	300 x 360	1



1123 X 4	331144 X 1	604757 X1
		x30
340750 X 4	728 X8	434 X1
6 PANS 7x50	5x30	
732 X2	332169 X1	918 X2
GLUE		VBA TR 4v25
7961 X1	1629 X2	935 X4
		VBA SPAX TF 3x12



1



332169 X1

918 X 2




VBA TR 4v25

732 X1

GLUE





2

7961	X 1	935	X4	728	X4
		 VBA SPAX TF 3x12			5x30

163758 0 03-Mars-15



732 X1

GLUE






3

728	X4
	5x30






4

340750	X 4	434	X1
 6 PANS 7x50			







3 / 4

5



163758 0 03-Mars-15

6



7

