








MEUBLES

DEMEYERE

SAV
SPAREPARTS
KUNDEDIENST
POST VENTAS
SERVICE NA VERKOOP
SERVIZIO POST-VENDITA
SERVICO DEPOIS DE VENDA
SERWIS POGWARANCYJNY

361365

337989_01



1H 00 Mn



(FR)

SECURITE

IMPORTANT-A LIRE SOIGNEUSEMENT-A CONSERVER
POUR CONSULTATION ULTERIEURE

(GB)

CAUTION

IMPORTANT-TO BE READED CARREFULLY-TO BE
CONSERVED FOR LATER CONSULTATION

(DE)

SICHERHEITSVORSCHRIFTEN

WICHTIG-GENAU DURCHZULESEN-AUFZUBEWAHREN
FÜR SPÄTEREN GEBRAUCH

(ES)

SEGURIDAD

IMPORTANTE-LEER CON ATENCION-CONSERVAR
PARA CONSULTAS POSTERIORES

(NL)

VEILIGHEID

BELANGRIJK-ZORGVULDIGGELEZEN TE WORDEN-BEWAARD
TE WORDEN VOOR LATERE RAADPLEGING

(IT)

SICUREZZA

IMPORTANTE-DA LEGGERE ATTENTAMENTE-DA
CONSERVARE PER CONSULTAZIONE ULTERIORE

(PT)






SEGURANCA

IMPORTANTE-PARA LER COM ATENCAO-PARA
CONSERVAR PARA COOSULTA ULTERIOR
















(PL)


UWAGA

WAZNE-UWAZNIE PRZECZYTAĆ-ZACHOWAĆ
CELEM POZNIJSZYCH KONSULTACJI




FABRICATION FRANCAISE

360915	X4	333019	X2	333079	X2	340750	X5	112	X5
									
434	X1	729	X9	604757	X30	913	X8	360916	X2
									
360913	X2	8930	X2	949	X8	566	X3	569	X3
									
444	x2	706	X4	70	X6	71	X6	937	X2
									
732	x1	928	x4	935	X4	477	X1	354342	X2
									



1	70	X6
		



2

112

X4






928

X2




477

X1



G




D


3

729


X9



G



D





4

360915

X4

340750

X4




5

71

X4

360916



X2



6

732

X1

**2H00 MN**



7

71


X2



G





D








8

340750	X1	112	X1
			



9


949	X4	354342	X2
			




x2

x2


10	333019	X2
		




11	937	x2	444	x2	604757	X30
						





12

935	X4	477	X1
 			





13

333079	X2	949	X4	949	X1
  					




14

928	X2	477	X1	360913	X2	913	X4
							




15

913	X3
	4x30




16

949	X1	706	X4
			



17

566	X3	569	X3
			



18

913	X3
	4x30

