






MEUBLES

DEMEYERE

SAV
SPAREPARTS
KUNDERDIENST
POST VENTAS
SERVICE NA VERKOOP
SERVIZIO POST-VENDITA
SERVICO DEPOIS DE VENDA
SERWIS POGWARANCYJNY

361368

337996_00



0H 45 Mn



(FR)

SECURITE

IMPORTANT-A LIRE SOIGNEUSEMENT-A CONSERVER
POUR CONSULTATION ULTERIEURE

(GB)

CAUTION

IMPORTANT-TO BE READED CARREFULLY-TO BE
CONSERVED FOR LATER CONSULTATION

(DE)

SICHERHEITSVORSCHRIFTEN

WICHTIG-GENAU DURCHZULESEN-AUFZUBEWAHREN
FÜR SPÄTEREN GEBRAUCH

(ES)

SEGURIDAD

IMPORTANTE-LEER CON ATENCION-CONSERVAR
PARA CONSULTAS POSTERIORES

(NL)

VEILIGHEID

BELANGRIJK-ZORGVULDIGGELEZEN TE WORDEN-BEWAARD
TE WORDEN VOOR LATERE RAADPLEGING

(IT)

SICUREZZA

IMPORTANTE-DA LEGGERE ATTENTAMENTE-DA
CONSERVARE PER CONSULTAZIONE ULTERIORE

(PT)






SEGURANCA

IMPORTANTE-PARA LER COM ATENCAO-PARA
CONSERVAR PARA COOSULTA ULTERIOR







(PL)

UWAGA


WAZNE-UWAZNIE PRZECZYTAĆ-ZACHOWAĆ
CELEM POZNIEJSZYCH KONSULTACJI




FABRICATION FRANCAISE

360915	X8	333009	X4	333012	X4	340750	X8	360913	X2
									
434	X1	913	X4	8930	X2	949	X8	566	X2
		 4x30				 3.5x15			
569	X2	356725	X1	333016	X2	907	X4	706	X4
		 				 3x16			

1	333012	X4	949	X8	949	X2
			 3.5x15			



2	356725	X2	907	X4
	 			






3

340750

X4

360915

X4





4

340750

X4

360915



X4



5

333016



x2



6

333009

X4



7

360913


X2

913







X4

706

X4



Ø4



8

566

X2

569

X2

