








MEUBLES
DEMEYERE

SAV
SPAREPARTS
KUNDERDIENST
POST VENTAS
SERVICE NA VERKOOP
SERVIZIO POST-VENDITA
SERVICO DEPOIS DE VENDA
SERWIS POGWARANCYJNY

58852

989_00



1H 00 Mn



(FR)

SECURITE

IMPORTANT-A LIRE SOIGNEUSEMENT-A CONSERVER
POUR CONSULTATION ULTERIEURE

(GB)

CAUTION

IMPORTANT-TO BE READED CARREFULY-TO BE
CONSERVED FOR LATER CONSULTATION

(DE)

SICHERHEITSVORSCHRIFTEN

WICHTIG-GENAU DURCHZULESEN-AUFZUBEWAHREN
FÜR SPÄTEREN GEBRAUCH

(ES)

SEGURIDAD

IMPORTANTE-LEER CON ATENCION-CONSERVAR
PARA CONSULTAS POSTERIORES

(NL)

VEILIGHEID

BELANGRIJK-ZORGVULDIGGELEZEN TE WORDEN-BEWAARD
TE WORDEN VOOR LATERE RAADPLEGING

(IT)

SICUREZZA

IMPORTANTE-DA LEGGERE ATTENTAMENTE-DA
CONSERVARE PER CONSULTAZIONE ULTERIORE

(PT)






SEGURANCA

IMPORTANTE-PARA LER COM ATENCAO-PARA
CONSERVAR PARA COOSULTA ULTERIOR














(PL)


UWAGA

WAZNE-UWAZNIE PRZECZYTAC-ZACHOWAC
CELEM POZNIEJSZYCH KONSULTACJI



FABRICATION FRANCAISE



1107	X4	333019	X2	333079	X2	340750	X5	112	X5
									
434	X1	729	X9	604757	X30	913	X8	1625	340079
		 Ø8				 4x30		 X2	 X2
332124	X2	8930	X2	949	X8	566	X3	569	X3
				 3.5*15					
444	x2	706	X4	70	X6	71	X6	937	X2
								 3*20	
732	x1	928	x4	935	X4	477	X1	354342	X2
				 3*12					



G




D



1




70

X6



2

112	X4	928	X2	477	X1
					




G




D

3

729	X9
	



G



D





4

1107

X4

340750

X4




5

71

X4

1625



X2



6

732

X1

**2H00 MN**



7

71


X2



G



D





8

340750

X1

112

X1



9






949

X4

354342

X2

3.5x15





x2

x2






10


333055 X2




11



937 x2 444 x2 604757 X30



12	935 X4	477 X1
		








13	333012 X2	949 X4	949 X1
			




14


928	X2	477	X1	332124	X2	913	X4
							



1






2



3


15

913	X3
	4x30




16

949	X1	706	X4



17

566	X3	569	X3



18

913	X3
	4x30

